Weathertzation Assistance

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/20002BR-0138/1

Work Order Type: Weatherization

Audit Name: 20002BR-0138AUDIT

CLIENT INFORMATION

Client ID: 20002BR-0138

AGENCY INFORMATION

Agency: Bradley-Cleveland Community Services Agency

Agency Phone: (423) 479-4111

Address: 155 Sixth Street SE **Fax:** (423) 479-4113

Agency Contact: Bloodworth, William D. Work Phone:

Cell Phone: (423) 505-4585

Email Address: Darblood@comcast.net

Company Name & License Number:	
Contractor's Signature	

COMMENT

Certified Firm/Renovator Required

Site Built over basement Built approx 1962 Approx 1584 sqft

Client ID: 20002BR-0138

Measures

,		dercut doors to achieve pa diff across closed do			Componen	ts		1	Inspected
C		cut three bedroom doors a differential across closed o		throom	doors to ac	hieve les	s than		
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Labor	Undercut doors	Each	5					
C	Other Detail								
Ĩ									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:						<u> </u>		
	Mogeuro 2 Int	iltration Podetn			Componen	te			Inspected
		iltration Redctn I kitchen exhaust fan ceilin	ng penetra	tion an		rip sliding	glass		Inspected
C	omment Airsea	l kitchen exhaust fan ceilin	ng penetra		d weathersti	rip sliding		Actual	Inspected
<i>C</i>	omment Airsea door			tion an Oty 1	d weathersti	rip sliding	glass		
C # 10	door Material / Labor Miscellaneous	I kitchen exhaust fan ceilin Description / Comment	<i>Units</i> See	Qty	d weathersti	rip sliding		Actual	
C # 10	door Material / Labor Miscellaneous Supplies	I kitchen exhaust fan ceilin Description / Comment	<i>Units</i> See	Qty	d weathersti	rip sliding		Actual	
C # 10	door Material / Labor Miscellaneous Supplies	I kitchen exhaust fan ceilin Description / Comment	<i>Units</i> See	Qty	d weathersti	rip sliding		Actual	
# 10	door Material / Labor Miscellaneous Supplies	I kitchen exhaust fan ceilin Description / Comment	<i>Units</i> See	Qty 1	d weathersti	rip sliding	Qty	Actual	

Measure 3 DW	/H Pipe Insulation			Componen	ts			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Linear Foot	10					
2 Labor	DHW Pipe Insulation	Each	1					
3 Other	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 4 Flo	or Ins. R-19			Componen Estimated		ment	Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1584					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Measure 5 D\ Comment	VH Tank Insulation			Componen	ts		1	Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equipment	DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
3 Other	DHW Tank Insulation	Each	1					
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
Measure 6 Fit	x Improper Venting (Cloth	hes Dryer)	Componen				Inspected
Comment		hes Dryer)	Componen Estimated			Actual	Inspected
Comment	x Improper Venting (Cloth Description / Comment	hes Dryer	Qty	-		Qty		Inspected Total
	Description / Comment			Estimated		Qty	Actual	
Comment# Material / Labor1 Health and Safe	Description / Comment	Units	Qty	Estimated		Qty	Actual	
Comment# Material / Labor1 Health and Safe Items	Description / Comment ty Equipment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Health and Safe Items2 Labor	Description / Comment ty Equipment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Health and Safe Items2 Labor	Description / Comment ty Equipment	<i>Units</i> Each	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Health and Safe Items2 Labor	Description / Comment ty Equipment	Units Each Hour	Qty 1 1	Estimated			Actual	

Measure 7 Fix I Fan	mproper Venting Kitch	en Exhau	st	Componer	its			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	Equipment	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 8 Fix C	Other Water Heating Pro	oblem		Componer			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Equipment	Each	1					
	Install romex connector							
2 Labor	Labor	Hour	1					
Other Detail			1	1		7		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

	Measure 9 Insta	all Bathroom Exhaust F	an		Componen	its			Inspected
C	Comment Vent Un	it to the Exterior							
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Bathroom exhaust fan	Each	2					
2	Labor	Labor	Each	2					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Measure 10 Lead	I Safety for EPA-RRP c	omplianc	e	Componer Estimated			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Health and Safety Items	Lead safety for EPA- RRP compliance	Each	1					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

	Measure 11 PressureRelief Piping Needed				Componen	ts	Inspected			
C	Comment									
					Estimated	<u> </u>		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety Items	Pressure relief piping	Each	1						
2	Labor	Labor	Each	1						
(Other Detail									
L										
				Measur	e Sub Total:			Sub Total:		
Ī	Field Notes:									
L										
			Work Or	der Gra	nd Total:		Gran	d Total:		